

UNCLASSIFIED

AD NUMBER

ADB971411

CLASSIFICATION CHANGES

TO: **unclassified**

FROM: **restricted**

LIMITATION CHANGES

TO:  
**Approved for public release, distribution  
unlimited**

FROM:  
**Distribution: DTIC users only.**

AUTHORITY

**E.O. 10501, 5 Nov 1953; AFMC ltr, 19 Feb  
2002**

THIS PAGE IS UNCLASSIFIED

5480

UNANNOUNCED

~~RESTRICTED~~  
**FOUO**  
OF

①  
MASTER FILE

AD-B971 411



# AIR PROVING GROUND

EGLIN AIR FORCE BASE, FLORIDA

TEST CONDUCTED BY  
EGLIN AIR FORCE BASE, FLORIDA

DTIC  
ELECTE  
OCT 27 1993  
S B D

SUBJECT

OPERATIONAL SUITABILITY TEST OF OPEN GUN PORTS FOR F-86  
AIRCRAFT

DECLASSIFIED  
DOB DIR 5200.9

PROJECT NO

DATE

24913 - - - 5

31 AUGUST 1949

"DTIC USERS ONLY"

COPY NO. 11

NO. OF PAGES

28

93-25299



**FOUO**

~~RESTRICTED~~  
UNCLASSIFIED

93

10

20042

3075

1361007 24913 - - - 5

THIS REPORT IS AN INFORMATION COPY.  
NO CONCLUSIVE ACTION WILL BE TAKEN  
THEREON UNTIL SUCH TIME AS APPROVAL  
LETTER FROM HEADQUARTERS, UNITED STATES  
AIR FORCES, HAS BEEN RECEIVED AND  
INCORPORATED THEREIN.

DTIC QUALITY INSPECTED 2

Accession For	
EXIS GRA&I	<input type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input checked="" type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
12	

**RESTRICTED**


**HEADQUARTERS  
AIR PROVING GROUND  
Eglin Air Force Base, Florida**

31 August 1949

**PROJECT NO. 24913—5**

**OPERATIONAL SUITABILITY TEST OF OPEN GUN PORTS FOR F-86  
AIRCRAFT**

1. Inclosed herewith is Final Report of Air Proving Ground, Eglin Air Force Base, Florida, subject as above.
2. Object: To determine the operational suitability at normal temperatures of the open gun ports for F-86 aircraft as compared to automatic gun muzzle door installations.
3. Description: The open gun ports installed on F-86 type aircraft are conventional grooved blast plates located at the forward end of each caliber .50 gun compartment.
4. Synopsis: It was concluded that open gun ports are more desirable for use on F-86 aircraft than automatic gun muzzle doors. It was also concluded that the type open gun port panels used for the test were satisfactory for service use on F-86 type aircraft. It was recommended that open gun ports be standardized for use on all F-86 type aircraft and that panels be provided as soon as possible to replace the present panel housing the automatic gun muzzle doors used on current F-86 aircraft.
5. Inclosures:
  - 1 - Copy of Directive
  - 2 - Final Report

  
W. E. KEPNER  
Major General, USAF  
Commanding

**RESTRICTED**

**RESTRICTED**

DSA 48

EDAL83  
RR JEJRG

FM JEDC 22J/CG AMC WRIGHT-PATTERSON AFB OHIO 042210Z  
TO CG AIR PROVING GROUND EGLIN AF BASE FLORIDA

AF GRNC

MCPXA42-5-8 CONTRACT AC-16013 F-86A AIRPLANES INSTALLATION  
OF FLUSH GUN PORT PANELS TO PROVIDE FOR AN ALTERNATE INSTALLATION  
TO THE GUN PORT DOOR ARRANGEMENT ON THE F-86A AIRPLANE IN CASE OF  
CONTINUED FAILURES NORTH AMERICAN AVIATION HAS BEEN REQUESTED TO FURNISH  
TO YOUR COMMAND ONE SET OF SIDE PANELS WITH FLUSH OPEN PORTS PD IT  
IS SUGGESTED THAT THESE PANELS BE PLACED ON ONE OF THE F-86A AIRPLANES  
UNDERGOING GUNFIRE TESTS AND FIRED A FULL 10,000 ROUND PER GUN COM-  
PLEMENT IN AN EFFORT TO HAVE THEM APPROVED FOR INSTALLATION AT A  
LATER DATE SHOULD THIS PROVE NECESSARY SIGNED PROCUREMENT DIVISION

CFN MCPXA42-5-8 AC-16013 F-86A F-86A F-86A 10,000

04/2210Z

C O P Y

Inclosure 1

**RESTRICTED**

Proj. No. 24913-5  
Page 2 of 28

**RESTRICTED**

HEADQUARTERS  
AIR PROVING GROUND  
Eglin Air Force Base, Florida

**FINAL REPORT**

**ON**

**OPERATIONAL SUITABILITY TEST OF OPEN GUN PORTS FOR F-86  
AIRCRAFT**

**PROJECT NO. 24913—5**

Inclosure 2

**RESTRICTED**

Proj. No. 24913—5  
Page 3

# RESTRICTED

## INDEX

	Page
1. OBJECT:	5
2. INTRODUCTION:	5
a. General:	5
b. Purpose:	5
c. Description:	5
d. Condition of Test:	7
3. CONCLUSIONS:	7
4. RECOMMENDATIONS:	7
5. DISCUSSION:	7
a. General:	7
b. Summary of Results:	8
6. INCLOSURES:	
1 - Test Historical Data	14
2 - Gun History Records Analysis	15
DISTRIBUTION:	26

## RESTRICTED

### 1. OBJECT:


To determine the operational suitability at normal temperatures of the open gun ports for F-86 aircraft as compared to automatic gun muzzle door installations.

### 2. INTRODUCTION:

a. General: The gun muzzle doors presently installed on F-86 type aircraft have previously been considered unsatisfactory due to maintenance difficulties and unsafe flying conditions involved during firing, caused by "cook-offs" and occasional loss of gun muzzle doors.

b. Purpose: This test was activated to provide a comparison between the open gun ports and the flush gun muzzle doors which are currently being installed on F-86 aircraft.


c. Description: The open gun ports are conventional grooved blast plates riveted and welded to the two stainless steel panels located forward of each gun compartment (see photographs 1, 2 and 3 below).



PHOTOGRAPH 1: Outside view of open gun port panel



RESTRICTED



PHOTOGRAPH 2: Inside view of open gun port panel



PHOTOGRAPH 3: Open gun port panel installed on F-86 airplane

RESTRICTED

Proj. No. 24913--5  
Page 6

## RESTRICTED

d. Conditions of Test: This test was conducted under ambient temperatures encountered between 0 and 40,000 feet altitudes. Cold soaking of installation before firing at extreme altitudes was not extended over five minutes duration due to the limited amount of fuel available.

### 3. CONCLUSIONS:

a. Open gun ports are more desirable for use on F-86 aircraft than the presently used automatic gun muzzle door installation.

b. The open gun port panels as tested are satisfactory for service use on F-86 aircraft.

### 4. RECOMMENDATIONS:

a. Open gun ports be standardized for use on all F-86 type aircraft.

b. Open gun port panels be provided as soon as possible to replace the present panel housing the automatic gun muzzle doors.

### 5. DISCUSSION:

#### a. General:

(1) A total of 60,116 rounds of ammunition was fired through the open gun port installation used for this test. Forty separate firing missions were utilized during the overall testing. One was a ground firing mission to determine trouble-free operation of the armament system, six were air-to-ground firing missions, two were air-to-air firing on towed targets, and 31 were air free firing missions at various altitudes up to and including 40,000 feet, one of which was at night to determine the blinding effect of muzzle flash on the pilot.


(2) All firing was accomplished in approximately 40- to 50-round bursts with cooling intervals from 2 to 3 minutes between bursts. Indicated air-speeds ranged from 180 to 560 mph.

## RESTRICTED

### b. Summary of Results:

- (1) Pilots flying the F-86 with open gun ports, who had previously flown F-86 aircraft with flush gun muzzle door ports, reported that there was no noticeable difference in handling characteristics of the airplane due to the open gun ports.
- (2) No maintenance was required on the open gun ports other than cleaning off burned powder and tightening of the filister head screws which vibrated loose during each firing mission. Considerable maintenance was required on the flush gun muzzle door installations used in Project No. 6484----5, "Operational Suitability Test of the F-86A Airplane." This maintenance was mainly due to occasional loss of gun muzzle doors, adjustment required for proper operation of door actuator motors and the time required to properly clean the gun muzzle doors and their accessory equipment. It was also noted that the filister head screws, which held the gun muzzle door panel to the airplane, had to be tightened after each firing mission.
- (3) The time required to install both open gun port panels on F-86 aircraft took two men an average time of 40 minutes. Panels could be removed by two men in 30 minutes. Installation and removal of flush gun muzzle port panels took approximately 10 minutes longer for each operation.
- (4) The suitability of the structure and materials of the open gun port panels was adequate with the exception of the filister head screws which held the panel to the airplane fuselage. Some of these screws were observed to be loose after every firing mission. Damage was encountered, however, to the skin section just below the open gun port panel on the right side of the airplane after a total of only 7,153 rounds had been fired through the installation. The arrows on Photograph 4 below, point to places where the .030 thickness skin was cracked.

RESTRICTED




PHOTOGRAPH 4

It is believed that the cracks shown above were a result of gun vibration during high speed firing missions. This discrepancy was remedied by having a strip of .030 thickness skin riveted on top of the cracked portion (see Photograph 5 below).

RESTRICTED

Proj. No. 24913--5  
Page 9

RESTRICTED



PHOTOGRAPH 5

It was also noted that the gunsight and radar access compartment cover, shown in Photograph 6 below, revealed a large inside crack after 44,900 rounds had been fired through the installation. This crack was welded together but would not hold for any sufficient length of time.

RESTRICTED

Proj. No. 24913—5  
Page 10

RESTRICTED



PHOTOGRAPH 6: Gunsight and radar access compartment cover

- (5) There were 82 "cook-offs" recorded during the overall testing of the open gun port panels. This large number of "cook-offs" was in part due to the short cooling interval (from 2 to 3 minutes) between average burst lengths from 40 to 50 rounds. Mission reports indicate that more "cook-offs" occurred when using two-second bursts with three minute cooling intervals than when using 2-1/2-second bursts with a cooling interval of two minutes. However, the cooling interval in both cases was considered too short for proper cooling of guns in the F-86 type aircraft. It is believed that the F-86 does not have sufficient air circulation for gun cooling when using either open or closed gun ports. No record was kept on the number of "cook-offs" that occurred in Project No. 6484--5, where gun muzzle doors were used; however, pilots that flew gunnery missions on that project reported that "cook-offs" were excessive.

RESTRICTED

**RESTRICTED**

- (6) The night blindness test mission revealed that the pilot was blinded approximately 3-1/2 seconds after each firing burst when using the open gun ports. No night blindness test was made when using closed gun ports.

6. INCLOSURES:

- 1 - Test Historical Data
- 2 - Gun History Records Analysis

RESTRICTED

PROJECT NO. 24913--5

Prepared by:

Junius G. McDonald  
JUNIOUS G. MCDONALD  
1st Lt, USAF  
Project Officer

Concurred in:

Raymond E. Evans  
RAYMOND E. EVANS  
Captain, USAF  
Test Officer

Approved by:

Charles F. Upson, Jr.  
LINUS F. UPSON, JR.  
Major, USAF  
Acting Chief, Weapons Projects  
Branch

Approved by:

James T. Stewart  
JAMES T. STEWART  
Lt Colonel, USAF  
Chief, Proof Test Division

Approved by:

K. K. Compton  
K. K. COMPTON  
Colonel, USAF  
Deputy for Operations

W. E. Kepner  
W. E. KEPNER  
Major General, USAF  
Commanding

Proj. No. 24913--5  
Page 13

RESTRICTED



**RESTRICTED**

**TEST HISTORICAL DATA**

**APG PROJECT NO. 24913—5**

1. **AUTHORITY:** Teletype from AMC (MCPXA42-5-8) 4 April 1949
2. **ACTIVATION DATE:** 6 June 1949
3. **EQUIPMENT RECEIVED:** 4 June 1949
4. **SUSPENSIONS:** None
5. **COMPLETION:** 19 August 1949 (Physical Testing)
6. **FLYING HOURS:** 29:40
7. **GROUND HOURS:** 200
8. **CLIMATIC CONDITIONS:** Temperate
9. **RELATED PROJECTS:** APG Project No. 6484—5, "Operational Suitability Test of F-86A Airplane"

**Inclosure 1**

**RESTRICTED**

**Proj. No. 24913—5**  
**Page 14**

RESTRICTED

TABLE I

SUMMARY OF THE AIR AND GROUND FIRING OF SIX CAL. .50 M3 MACHINE GUNS  
MOUNTED IN AN F-86 AIRCRAFT WITH A G-9 SOLENOID

Serial Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
2056162	L #1	540	540	Air-to- Ground	--	E-3	Link chute jam.
		1347	807	Air-to- Ground	--	?-4	Failure to fire; Ground check OK; no reason for not firing.
		4386	465	30,000	--	E-3	Link jam in mouth of link chute.
		4965	1044	30,000	2.5-4.0	G-3	Light struck primer; flat firing pin; changed pin.
		5219	1298	30,000	--	?-1	Light struck primer; changed sear.
		6114	2193	30,000	2.5-4.5	?-3	Failure to chamber round.
		6476	2555	30000- 35000	--	?-1	Light struck primer. Changed bolt, firing pin extension, belt feed lever, cocking lever, and receiver cover.
		6696	2770	1,000- 5,000	--	?-1	Light struck primer; primer swelled in case due to excess heat.

RESTRICTED

RESTRICTED

TABLE I (Cont'd)

Serial No. of Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
7585		3659	40,000	--	G-1		Light struck primer; brass in firing pin port.
7806		3880	1,000- 10,000	--	G-1		Light struck primer; brass in firing pin port.
8385		4479	15,000	--	?-1		Light struck primer.
8787		4881	15,000	--	?-1		Believe to be light struck primer followed by cookoff.
9105		5299	10,000	--	?-3		Failure to feed; ground check OK.
300	2125320 L #2	300	Ground	--	?-3		Failure to feed; reason unknown.
376		376	Air-To- Ground	--	M		Failure to extract from chamber; rusty barrel.
678		302	Air-To- Ground	--	?-1		Light struck primer.
803		427	Air-To- Ground	--	?-6		Failure to extract from feedway; short round; bolt hit base of round.
1855		1479	20,000	--	?-3		Failure to chamber round; 12 o'clock stub.
3614		3238	30,000	--	E-2		Feed chute jam; feed chute came loose at base of feed chute.
4917		4741	30,000	2.5-4.5	M		Ejector on wrong side of extractor.

RESTRICTED

RESTRICTED

TABLE I (Cont'd)

Serial No. of Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
2124032	L #3	5723	5347	1,000- 5,000	--	?-6	Bolt hit base of cart- ridge; short round.
		6208	5832	1,000- 5,000	--	G-1	Light struck primer; brass in firing pin port.
		672	672	Air-To- Ground	--	E-2	Barrels changed to modified bullet seat.
		3227	2555	10,000	--	E-3	Feed chute jam.
		3230	2558	17,000	--	?-1	Belt feed slide jam- med on guide of link chute.
		3783	3111	17,000	--	?-1	Light struck primer; changed bolt switch.
		4126	3454	30,000	--	?-7	Light struck primer. T-slot pulled lip of cartridge; left spent case in chamber;
		4336	210	30,000	--	?-7	changed barrel and bolt.
		6022	1796	40,000	--	?-3	T-slot pulled lip of cartridge; left spent case in chamber.
							Failure to feed in chamber; short round.

RESTRICTED

RESTRICTED

TABLE I (Cont'd)

Serial No. of Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
6315		2089		30,000- 35,000	--	G-2	Light struck primer; broken sear. Follow- ing parts changed: belt feed lever, fir- ing pin extension, sear cocking lever, bolt switch, extrac- tor, breech lock, and belt feed pawl.
9005		5779		15,000	--	G-1	Light struck primer; brass in firing pin port.
10190		6964		10,000	--	E-2	Failure to feed; feed chute came loose at base of chute.
2056447	R #1	558	558	Air-To- Ground	--	E-3	Link chute jam.
		574	16	Air-to- Ground	--	E-1	Solenoid out of time. Barrels changed to modified bullet seat.
		2827	2269	10,000	--	?-1	Light struck primer; cause undetermined.
		3561	3003	17,000	--	A-3	Separated round in feedway.
		4376	815	30,000	--	?-7	T-slot pulled lip of cartridge; left spent case in chamber.

RESTRICTED

RESTRICTED

TABLE I (Cont'd)

Serial No. of Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
2123755	R #2	4989	1428	4,000- 10,000	--	?-4	Gun stopped out of battery; no reason for not firing.
		6936	3375	1,000- 5,000	--	G-1	(Night firing). Light struck primer; brass in firing pin port.
		7162	3601	40,000	--	?-6	Failure to extract round from belt.
		9828	6267	10,000	--	G-1	Light struck primer; brass in firing pin port.
		300	300	Ground	--	?-3	Empty chamber - 185 round. Modified belt feed pawl installed.
		372	372	Air-to- Ground	--	M	Failure to extract from chamber; rusty barrel.
		374	2	Air-to- Ground	--	G-4	Barrel changed to modified bullet seat.
		2243	1871	15,000	--	E-3	Failure to feed; ex- tractor failed to secure round while being chambered.
		3101	2729	17,000	--	?-1	Link jam in face of chute.
							Light struck primer.

RESTRICTED

TABLE I (Cont'd)

Serial No. of Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
		3362	2990	17,000	--	?-3	Bolt 1/2-inch out of battery; no reason.
		5085	1723	4,000-10,000	--	?-6	Failure to extract from belt (night firing).
		5658	2296	30,000	2.5-4.5	?-1	Light struck primer; changed sear.
		7130	3768	1,000-5,000	--	G-1	Light struck primer; brass in firing pin port.
		7439	4077	1,000-10,000	--	E-2	Feed chute came loose at base of chute.
		9530	7268	10,000	--	G-1	Light struck primer; brass in firing pin port.
2122161	R #3	300	300	Ground	--	?-6	Short round - 225th round; bolt hit round.
		638	638	Air-to-Ground	--	?-6	Failure to extract from feedway.
		963	325	Air-to-Ground	--	G-1	Failure to fire caused by primer blow back.
		1508	870	30,000	--	?-1	Light struck primer.
		1680	1042	1,000	--	?-1	Light struck primer; Changed sear, firing pin and extractor.

RESTRICTED

RESTRICTED

TABLE I (CONT'D)

Serial No. of Gun	Location of Gun in A/C	No. Rds. Fired Through Gun	No. Rds. Fired Through Brl	Altitude (Feet)	No. of G's	Mal- function	Remarks
		1699	1061	1,000	—	E-1	Solenoid out of time; replaced.
		3342	2704	17,000	—	G-3	Light struck primer; flat firing pin; fir- ing pin and barrel changed.
		6135	2793	30,000- 35,000	—	A-1	Failure to extract from belt; short round; changed firing pin extension, belt feed slide pawl, cock- ing lever, and re- ceiver cover.
		6963	3621	1,000- 5,000	—	G-1	Light struck primer; brass in firing pin ports.
		7852	4510	1,000- 10,000	—	?-1	Light struck primer followed by a cook- off. Ground check OK.
		9955	6613	10,000	—	G-2	Failure to fire; broken firing pin.

NOTE: All six guns were manufactured by High Standard.



RESTRICTED

TABLE II

SUMMARY OF ROUNDS LOADED AND FIRED ON THE GROUND, AIR-TO-GROUND AND FROM 1,000 TO 40,000 FEET ALTITUDE, SHOWING NUMBER OF MALFUNCTIONS FOR EACH CONDITION:  
ALSO PERCENTAGE OF ROUNDS FIRED FOR EACH CONDITION.

No. Missions Altitude	1		2		6		4	
	Ground		1,000		None Given		None Given	
No. G's	3		2		7		4	
No. Malfunctions	12		3600		10,800		7200	
No. Rds. Loaded	1800		3191		10,102		6140	
No. Rds. Fired	1800		4887		93.5%		85.3%	
% Fired	100%		67.9%					

No. Missions Altitude	3		2		6		2	
	17,000		30,000		None Given		40,000	
No. G's	None Given		2.5 to 4.5		None Given		None Given	
No. Malfunctions	6		4		7		3	
No. Rds. Loaded	5400		3600		10,800		3600	
No. Rds. Fired	4765		3250		9,921		3301	
% Fired	88.2%		90.3%		91.9%		91.7%	

No. Missions Altitude	1		2		1		2	
	1000-4000		1000-5000		1000-10,000		30,000-35,000	
No. G's	None Given		None Given		None Given		None Given	
No. Malfunctions	2		6		3		0	
No. Rds. Loaded	1800		5400		3600		1800	
No. Rds. Fired	1436		4658		3219		1348	
% Fired	79.8%		86.3%		89.4%		74.9%	

Demonstration		Minimum	
2		None Given	
0		450	
446		99.1%	

RESTRICTED

RESTRICTED

TABLE III

RELATIONSHIP BETWEEN LOCATION OF CAL. .50 M3 MACHINE GUN  
MOUNTED IN AN F-86A AND TYPE OF STOPPAGE

Malfunction	L#1	L#2	L#3	R#1	R#2	R#3
(A) Ammunition						
(A-1) Short round						1
(A-3) Defective or bent round				1		
(G) Gun						
(G-1) Light struck primer	2	1	1	2	2	2
(G-2) Broken parts			1			1
(G-3) Worn or bent parts	1					1
(G-4) Improper functioning of parts					1	
(M) Maintenance Personnel		2			1	
(E) Related Equipment						
(E-1) Firing solenoid				1		1
(E-2) Feed chutes		1	2		1	
(E-3) Link chutes	2		1	1	1	
(?) Responsibility Undetermined						
(?-1) Light struck primer	5	1	2	1	2	3
(?-3) Failure to feed into chamber	2	2	1		2	
(?-4) Failure to fire	1			1		
(?-6) Failure to extract round from belt		2		1	1	2
(?-7) Failure to extract round from chamber			2			

RESTRICTED

# RESTRICTED

TABLE IV

CAUSES FOR THE SIXTY-THREE MALFUNCTIONS  
OF SIX CAL. .50 M3 MACHINE GUNS MOUNTED IN AN F-86A AIRCRAFT

<u>Stoppages</u>	<u>Causes</u>
	I (A) Ammunition
1	(A-1) Short round
1	(A-3) Defective or bent round
	II (G) Gun
10	(G-1) Light struck primer
2	(G-2) Broken parts
2	(G-3) Worn or bent parts
1	(G-4) Improper functioning of parts
3	III (M) Maintenance Personnel
	IV (E) Related Equipment
2	(E-1) Firing solenoid
4	(E-2) Feed chutes
5	(E-3) Link chutes
	V (?) Responsibility Undetermined
14	(?-1) Light struck primer
7	(?-3) Failure to feed into chamber
2	(?-4) Failure to fire
6	(?-6) Failure to extract round from belt
3	(?-7) Failure to extract round from chamber
<hr/> 63	Total

RESTRICTED

TABLE V

SUMMARY OF ROUNDS LOADED AND FIRED  
FOR EACH OF SIX CAL. .50 M3 MACHINE GUNS MOUNTED IN AN F-86A

	Gun Number					
	L #1	L #2	L #3	R #1	R #2	R #3
	2056162	2125320	2124032	2056447	2123755	2122161
Rounds Loaded	11,475	11,475	11,475	11,475	11,475	11,475
Rounds Fired	10,005	9,508	10,390	10,128	10,130	9,955
% Fired	87.2%	82.9%	90.5%	88.3%	88.3%	86.8%

RESTRICTED

**RESTRICTED**

**HEADQUARTERS  
AIR PROVING GROUND  
Eglin Air Force Base, Florida**

**PROJECT DISTRIBUTION LIST**

**PROJECT NO. 24913---5**

**OPERATIONAL SUITABILITY TEST OF OPEN GUN PORTS FOR F-86 AIRCRAFT**

	<u>Quantity</u>
The Air Adjutant General, USAF, Washington 25, D. C.	
Attn: Air Force Document Reference and Research Br.	2
Dir of Intelligence, Hqs, USAF, Washington 25, D. C.	1
Research & Development Board, Washington 25, D. C.	
Attn: Air Force Secretary	3
Director of Training and Requirements, Attn: Requirements Division, Hqs, USAF, Washington 25, D. C.	10
Office of Chief of Ordnance, Washington 25, D. C.	
Attn: ORDTX-AR	2
Dir of Program Standards & Cost Control, Comptroller, Hqs USAF, Washington 25, D. C. (AFAPA-3C)	1
Office of Operations Analysis, DCS/O, Hqs, USAF, Washington 25, D. C. (AFOOA)	1
Plans, Programs & Policy Division, DCS/M (AFMPP), Hqs USAF, Washington 25, D. C.	2
CG, Caribbean Air Command, Albrook AF Base, Canal Zone, Attn: DCS/M	3
CG, Newfoundland Base Command, APO 862, c/o PM, New York, Attn: A-3	3
CG, AMC, Wright-Patterson AF Base, Dayton, Ohio, Attn: MCREOC (Mr. R. E. Teter)	10
CG, AMC, Wright-Patterson AF Base, Dayton, Ohio Attn: MCPPXA-42	1
CG, AMC, Wright-Patterson AF Base, Dayton, Ohio Attn: APG Liaison Officer	1
CG, AMC, Wright-Patterson AF Base, Dayton, Ohio Attn: CADO	1
CG, Strategic Air Command, Offutt AF Base, Omaha, Neb.	2
CG, Tactical Air Command, Langley AF Base, Va.	2
CG, Continental Air Command, Mitchel AF Base, N. Y.	1
CG, Air Defense Command, Mitchel AF Base, N. Y.	1
CG, Alaskan Air Command, APO 942, c/o PM Seattle, Wash., Attn: Maintenance Division, DCS/M	3
CG, Aberdeen Proving Ground, Md., Attn: Tech. Info. Sec.	1
Hq, Aberdeen Proving Ground, Md., Attn: AMC Engineering Field Office	1

Proj. No. 24913---5

Page 26

**RESTRICTED**

# RESTRICTED

	<u>Quantity</u>
Ballistic Research Lab., Aberdeen Proving Ground, Md., Attn: Dr. T. E. Sterne	1
14th Air Force Hqs, Orlando, Fla., Attn: Armament Officer, Captain Albert I. Fisher	1
CG, 8th Air Force, Carswell AF Base, Ft. Worth, Tex.	1
CG, USAF in Europe, APO 633, c/o PM, N. Y.	2
CG, 3415th Technical Training Wing, Lowry AF Base, Denver, Colo., Attn: Wing Operations Division	2
CG, 307th Bombardment Wing Medium, MacDill AF Base, Tampa 8, Fla., Attn: Wing Air Inspector	1
Wing Commander, 51st Fighter Wing, APO 239, Unit 2, c/o PM San Francisco	2
CO, 3525th Pilot Training Wing (Adv SE), Williams AF Base, Chandler, Ariz., Attn: Training Research and Development Dept.	2
Hq & Hq 36th Fighter Wing, FAFB, APO 208, c/o PM. N. Y., Attn: Armament Ordnance Officer, Maj J P Lappin	1
CG, 5001st Wing, APO 731, c/o PM Seattle Wash.	2
Air University Library, Maxwell AF Base, Alabama	5
CG, Air Tactical School, Tyndall AF Base, Fla.	1
CG, USAF Field Office for Atomic Energy, Kirtland AF Base, N.M., Attn: Library Officer	1
CO, Las Vegas AF Base, Las Vegas, Nev.	2
CG, Flying Training Division, ATRC, Randolph AF Base, Texas, Attn: Training Development	1
CO, USAF Aircraft Gunnery School, Las Vegas AF Base, Nev.	1
CG, 311th Air Division, Topeka AF Base, Topeka, Kansas	4
CO, 3499th Mobile Training Group, Chanute AF Base, Ill.	1
CG, Technical Division, ATRC, Scott AF Base, Ill.	1
CO, 20th Fighter Group, Shaw AF Base, So. Carolina	3
Wing Ordnance Officer, Howard AF Base, Canal Zone, Attn: Captain J. R. Langley	2
CO, Walker AF Base, N. M., Attn: Armament Officer	1
CG, Command & General Staff College, Ft. Leavenworth, Kansas, Attn: Chief, Air Force Section	1
M.I.T., Cambridge 39, Mass., Attn: Prof. J. R. Markham, Dir. Supersonic Lab. (Room 80-209)	1
M.I.T. Instrument Lab., Cambridge 39, Mass., Hood Bldg., Attn: Miss Mead	1
Rand Corporation, 1500 Fourth St., Santa Monica, Cal., Attn: Philip D. Doersam	1
Chief, Flying Safety Division, Office of the Air Inspector, c/o Inspector General, USAF, First Region, Langley AF Base, Va.	1
Deputy/Operations File, APG, Eglin AF Base, Fla.	1
Weapons Projects Branch, PTD, APG, Eglin AF Base, Fla.	1
Air Armament Officer, APG, Eglin AF Base, Fla.	1

Proj. No. 24913-5  
Page 27

# RESTRICTED

# RESTRICTED

	<u>Quantity</u>
CO, U.S. Naval Proving Ground, Dahlgren, Va.	1
MCATS, Attn. Major H. R. Jordan, USMC, Marine Corps Schools, Quantico, Va.	1
CO, VMF 311, Marine Corps Air Station, El Toro (Santa Ana) Cal.	1
Cdr. U.S. Naval Air Test Center, Patuxent River, Md., Attn: Armament Test	1
Cdr. U.S. Naval Ordnance Test Center, Attn: Tech. Lib. Sec., Inyokern, Cal., P.O. China Lake, Cal.	1
CO, U.S. Naval Air Station (Aero. Pub. Lib.), Patuxent River, Md.	1
Cdr. Fleet Air West Coast, U.S. Pacific Fleet Air Force, U.S. Naval Air Station, San Diego, Cal.	1
C.O., U.S. Naval Ordnance Plant, Indianapolis 6, Ind.	1
Chief of Naval Operations (Op-551) Room 2910, Navy Dept., Washington 25, D. C.	1
Cdr. U.S. Naval Ordnance Lab., White Oak, Silver Springs 19, Md.	1
COMOPDEVFOR, USS ADIRONDACK, (E-AGC-15) Flagship U.S. Naval Base, Norfolk 11, Va.	1
Commandant of the Marine Corps, Hqs USMC, Washington 25, D. C.	1
Chief Bureau of Aeronautics (Aer-TD-41) Navy Dept., Washington 25, D. C.	2
Chief of the Bureau of Ordnance (Re.8) Navy Dept., Washington 25, D. C.	2
Naval Liaison Officer, APG, Eglin AF Base, Fla.	1

RESTRICTED

Proj. No. 24913-5  
Page 28 of 28



DEPARTMENT OF THE AIR FORCE  
HEADQUARTERS AIR FORCE MATERIEL COMMAND  
WRIGHT-PATTERSON AIR FORCE BASE OHIO

FEB 19 2002

MEMORANDUM FOR DTIC/OCQ (ZENA ROGERS)  
8725 JOHN J. KINGMAN ROAD, SUITE 0944  
FORT BELVOIR VA 22060-6218

FROM: AFMC CSO/SCOC  
4225 Logistics Avenue, Room S132  
Wright-Patterson AFB OH 45433-5714

SUBJECT: Technical Reports Cleared for Public Release

→ References: (a) HQ AFMC/PAX Memo, 26 Nov 01, Security and Policy Review,  
AFMC 01-242 (Atch 1)

(b) HQ AFMC/PAX Memo, 19 Dec 01, Security and Policy Review,  
AFMC 01-275 (Atch 2)

(c) HQ AFMC/PAX Memo, 17 Jan 02, Security and Policy Review,  
AFMC 02-005 (Atch 3)

1. Technical reports submitted in the attached references listed above are cleared for public release in accordance with AFI 35-101, 26 Jul 01, *Public Affairs Policies and Procedures*, Chapter 15 (Cases AFMC 01-242, AFMC 01-275, & AFMC 02-005).

2. Please direct further questions to Lezora U. Nobles, AFMC CSO/SCOC, DSN 787-8583.

LEZORA U. NOBLES  
AFMC STINFO Assistant  
Directorate of Communications and Information

Attachments:

1. HQ AFMC/PAX Memo, 26 Nov 01
2. HQ AFMC/PAX Memo, 19 Dec 01
3. HQ AFMC/PAX Memo, 17 Jan 02

cc:

HQ AFMC/HO (Dr. William Elliott)





# DEPARTMENT OF THE AIR FORCE

HEADQUARTERS AIR FORCE MATERIEL COMMAND  
WRIGHT-PATTERSON AIR FORCE BASE OHIO


NOV 26 2001

MEMORANDUM FOR HQ AFMC/HO

FROM: HQ AFMC/PAX

SUBJECT: Security and Policy Review, AFMC 01-242

1. The following material has been reviewed for security and policy LAW AFI 35-101, Chapter 15. It is cleared for public release:
  - a. "Investigation of A-4 Sight in F-86E Airplane, 18 July 1952, DTIC No. AD-473 192
  - b. Operational Suitability Test of Open Gun Ports for F-86 Aircraft, 31 August 1949, DTIC No. AD-B971 411
  - c. Letter Report on Relative Aerial Combat of the F-84E Versus the F086A Capability, 30 January 1951, DTIC No. AD-B971 840.
2. Two reports require clearance from other organizations. Hypoxia and Undetermined Jet Accidents," will be reviewed by 311<sup>th</sup> Human Systems Wing, and "RCAF Ejection Experience," will be forward to Air Staff for coordination with RCAF.
3. If you have any questions, please call me at 77828. Thanks.

  
JAMES A. MORROW  
Security and Policy Review  
Office of Public Affairs

Attachment:  
Your Ltr 26 November 2001

26 November 2001

MEMORANDUM FOR: HQ AFMC/PAX  
Attn: Jim Morrow


FROM: HQ AFMC/HO

SUBJECT: Releasability Reviews

1. Please conduct public releasability reviews for the following attached Defense Technical Information Center (DTIC) reports:

- a. *Investigation of A-4 Sight in F-86E Airplane*, 18 July 1952; DTIC No. AD- 473 192.
- b. *Operational Suitability Test of Open Gun Ports for F-86 Aircraft*, 31 August 1949; DTIC No. AD-B971 411.
- c. *Hypoxia and Undetermined Jet Accidents*, 19 October 1956; DTIC No. AD-115 661.
- d. *Letter Report On Relative Aerial Combat Of The F-84E Versus The F-86A Capability*, 30 January 1951; DTIC No. AD-B971 840.
- e. *RCAF Ejection Experience, 1952-1961, 1965*; DTIC No. AD-465 171.

2. These attachments have been requested by Dr. Kenneth P. Werrell, a private researcher.
3. The AFMC/HO point of contact for these reviews is Dr. William Elliott, who may be reached at extension 77476.

  
JOHN D. WEBER  
Command Historian

5 Attachments:

- a. DTIC No. AD- 473 192
- b. DTIC No. AD-B971 411
- c. DTIC No. AD- 115 661
- d. DTIC No. AD-B971 840
- e. DTIC No. AD- 465 171

Cleared  
AFMC  
01-259

Cleared  
AFMC  
01-260